

NO	TGL	GI	PENYU LANG	JAM PADAM	JAM NYALA	LAMA PADAM	A	KV	DAYA HILANG	KWH HILANG	RELE KERJA	KODE	PENYEBAB	KODE	UNIT
1	1-Jan-15	Batang	BTG06	19:13	19:50	37	180	20.6	5137.8	3168.31	OCR >>		Pohon sengon menimpa jaringan dipole B6-53	41a	BTG
2	1-Jan-15	Batang	BTG02	19:45	20:45	60	140	20.3	3937.88	3937.88	GFR >>		Fuse link putus dipole B-210/83	41d-3	BTG
3	11-Jan-15	Batang	BTG07	18:25	19:55	90	227	20.4	6416.44	9624.65	OCR GFR Ø R >>	29	Tokek menempel di isolator dipole B-210/230	41b	BTG
4	19-Jan-15	Batang	BTG06	17:15	18:40	85	155	20.6	4424.22	6267.65	Tidak Termonitor	1	Antena menimpa jaringan dipole B6-177	41d	BTG
5	24-Jan-15	Batang	BTG01	9:50	10:36	46	115	20.5	3266.55	2504.36	Tidak Termonitor	1	Tiang telkom mengenai JTM 1 pns dipole B-210/70.A	41d	BTG
6	3-Feb-15	Batang	BTG06	6:17	6:43	26	59	20.5	1675.88	726.22	Tidak Termonitor		Burung mengenai arrester jaringan di B6-17	41b	BTG
7	7-Feb-15	Batang	BTG02	19:58	20:08	10	129	20.0	3574.85	595.81	CN >>		Bersamaan memasukan FCO dipole B-210/82	41d	BTG
8	18-Feb-15	Batang	BTG06	16:36	17:13	37	127	20.9	3677.8	2267.98	OCR Fasa B & N		Burung mengenai arrester jaringan dipole B6-17	41b	BTG
9	21-Feb-15	Batang	BTG01	4:08	5:12	64	104	20.7	2982.92	3181.78	Tidak Termonitor		Tiang patah tertabrak truk dipole B-196	41d	BTG
10	21-Feb-15	Batang	BTG09	4:08	5:13	65	130	20.7	3728.65	4039.37	OCR Fasa R		Tiang patah tertabrak truk dipole B-196	41d	BTG
11	4-Mar-15	Batang	BTG01	18:58	23:32	274	123	20.5	3494	15954.98	Tidak Termonitor		Petir	41c	BTG
12	4-Mar-15	Batang	BTG08	19:01	20:50	109	204	20.6	5823	10578.17	Tidak Termonitor		Tiang patah karena kerobohan pohon di B4-26, B4-27 & B4-28	41a	BTG
13	4-Mar-15	Batang	BTG07	19:01	20:47	106	242	20.3	6807	12025.52	OCR GFR Fasa S >> High Set 2		Tiang patah karena kerobohan pohon di B4-26, B4-27 & B4-28	41a	BTG
14	4-Mar-15	Batang	BTG03	19:03	23:19	256	128	20.3	3600	15361.46	Tidak Termonitor		Pohon sengon merobohi jaringan di B3-32 s/d B3-33	41a	BTG
15	4-Mar-15	Batang	BTG03	23:27	23:41	14	8	20.8	231	53.80	OCR Fasa R >> High Set 1		Bersamaan pemasukan recloser B3-75/2	47	BTG
16	20-Mar-15	Batang	BTG07	14:35	15:44	69	164	20.5	4658	5357.15	OCR Fasa S T >> High Set 1		Pohon sengon menimpa jaringan di B-210/34/1	41a	BTG
17	24-Mar-15	Batang	BTG04	14:43	15:25	42	298	20.9	8630	6040.86	OCR GFR Fasa S >> High Set 2		Sambungan kabel SKTM rusak di B4-56 (beban dilimpah ke BTG03)	51	BTG
18	28-Mar-15	Batang	BTG02	16:12	16:44	32	77	20.5	2187	1166.49	OCR Fasa S T >>		Burung dara di jaringan di B-210/135	41b	BTG
19	1-Apr-15	Batang	BTG06	2:24	2:38	14	118	20.5	3351.77	782.08	OCR GFR >>		TIDAK DIKETEMUKAN (HUJAN DISERTAI PETIR)	41c	BTG
20	5-Apr-15	Batang	BTG10	14:21	15:38	77	96	20.2	2686.96	3448.26	OCR GFR Ø R >>		KABEL SKUTM TERBAKAR DI B10-27 SAMPAI B10-28	51	BTG
21	15-Apr-15	Batang	BTG07	10:25	11:02	37	175	20.7	5019.34	3095.26	OCR Ø S,T >> High Set 1		POHON ROBOH MENGENAI JARINGAN DI B210/235/1	41a	BTG
22	2-May-15	Batang	BTG01	11:39	12:31	52	11	20.4	310.929	269.47	OCR GFR >>		ULAR Mengenai Jaringan	41b	BTG
23	3-May-15	Batang	BTG06	12:56	13:32	36	115	20.1	3202.81	1921.69	OCR GFR		Isolator Pecah Fasa S	45	BTG
24	5-May-15	Batang	BTG07	8:49	9:23	34	171	20.3	4809.83	2725.57	OCR GFR >> High Set 2		TALANG TERBANG MENGENAI JARINGAN DI B4-19	41d	BTG
25	27-May-15	Batang	BTG02	16:52	17:26	34	85	20.6	2426.19	1374.84	OCR Ø S,T >>		BURUNG DARAH	41b	BTG
26	4-Jun-15	Batang	BTG06	9:43	10:14	31			0	0.00	OCR GFR inst		Pohon ditebang merobohi jaringan di B6-46 s.d 47	41a	BTG

27	16-Jun-15	Batang	BTG03	21:54	22:41	47			0	0.00	-		Tikus mengenai jaringan di B3-75/2	41b	BTG
28	19-Jun-15	Batang	BTG06	4:00	4:56	56			0	0.00	OCR GFR inst		Isolator gosong di B6-81	45	BTG
29	20-Jul-15	Batang	BTG06	13:48	15:53	125	112	20.6	3196.86	6660.12	Tidak Termonitor		Isolator flashover di B6-11 (SEBAGIAN DILIMPAHKAN KE BTG09 PKL 14:06)	45	BTG
30	2-Sep-15	Batang	BTG04	0:07	1:02	55	267	20.0	7399.1	6782.51	Phs C		Kabel power BTG04 breakdown	51	BTG
31	4-Sep-15	Batang	BTG07	5:24	6:53	89	171	20.0	4738.75	7029.15	Hz 1 Phs A, B, C		Pohon pecut ditabrak truk mengenai jaringan di B-210/233	41d	BTG
32	10-Sep-15	Batang	BTG06	9:08	12:22	194	132	20.0	3657.98	11827.48	Phs B, C		Kawat gancet di B6-30 (sudah diresagging)	41d	BTG
33	7-Oct-15	Batang	BTG07	11:59	13:26	87	169				Phs A, B		Ranting pohon sengon di B-210/166.B/17	41a	BTG
34	9-Oct-15	Batang	BTG03	5:07	6:36	89	127				Phs A, B		Gangguan kubikel pelanggan PT Sukorintex pole B3-24/2	41d	BTG
35	10-Oct-15	Batang	BTG07	1:36	1:55	19					Phs B, C		SR putus mengenai JTM di B-210/196	41d	BTG
36	15-Oct-15	Batang	BTG02	9:57	10:07	10							Join feeder buka ABSW B-210/148 (recloser feeder join trip)	41d	BTG
37	16-Oct-15	Batang	BTG03	12:56	13:57	61					Phs B, C		Isolator suspension flashover di PT Ganda Maju Jaya B3-54.D	45	BTG
38	20-Nov-15	Batang	BTG01	22:16	0:25	129	60	21.1	1754.17	3771.46	OCR GFR Ø R,S,T		TRAFO TERGANGGU DI B-187 50 KVA, HUJAN LEBAT DISERTAI ANGIN KENCANG	82	BTG
39	20-Nov-15	Batang	BTG09	22:17	0:54	157	131	20.4	3702.88	9689.20	OCR GFR Ø S,T		TRAFO TERGANGGU DI B-187 50 KVA, HUJAN LEBAT DISERTAI ANGIN KENCANG	82	BTG
40	30-Nov-15	Batang	BTG01	22:10	0:26	136	120	20.6	3425.2	7763.79	Tidak Termonitor		TIDAK DITEMUKAN (BEBAN DILIMPAHKAN KE BTG01 PKL22:48)	82	BTG
41	30-Nov-15	Batang	BTG08	22:09	23:07	58	131	20.6	3739.18	3614.54	Tidak Termonitor		TIDAK DITEMUKANM (CUACA HUJAN DERAS DISERTAI PETIR)	82	BTG
42	12-Dec-15	Batang	BTG02	4:16	6:46	150	88	20.5	2499.62	6249.06	OCR GFR Ø S,T >>		ISOLATOR FLASHOVER DI B-210/30	45	BTG
43	12-Dec-15	Batang	BTG06	10:52	11:23	31	139	20.5	3948.27	2039.94	OCR GFR Ø T >>		BURUNG PADA BUSHING RECLOSER DI B6-39	41b	BTG
44	13-Dec-15	Batang	BTG01	4:41	5:59	78	104	20.3	2925.28	3802.86	OCR GFR >>		Konduktor Putus Tertabrak Truk	41d	BTG
45	15-Dec-15	Batang	BTG06	0:04	7:52	468	123	20.6	3510.83	27384.50	OCR GFR >>		ISOLATOR GUMPIL DIPOLE B6-25 (PUKUL 01:52 WIB BEBAN DILIMPAHKAN KE BTG09)	45	BTG
46	21-Dec-15	Batang	BTG01	17:02	17:11	9	68	20.5	1931.53	289.73	OCR GFR >>		POHON ROBOH DI B1-75-ZZI	41a	BTG

KLASIFIKASI	KODE	PENYEBAB	
KOMPONEN	41d-3	FCO PUTUS TIDAK DIKETAHUI PENYEBABNYA	4
	44b	JUMPER SUTM RUSAK	2
	44c	SUTM LEPAS DARI ISOLATOR	-
		JUMLAH	18
PERALATAN GARDU TIANG	45	ISOLATOR RUSAK	8
	47	POLE SWITCH RUSAK (ABSW,DS LOSS CONTACT)	5
	41d-1	TRAFO RUSAK	-
	56	SYMPATHETIC TRIPPING	-
	38	KERUSAKAN PADA TIANG KECUALI (ISOLATOR & PENGHANTAR)	-
		JUMLAH	16
ALAM	41c	PETIR	15
	85	GEMPA BUMI	-
	86	KEBAKARAN	-
	87	LAIN2 (KERUSUHAN MASSAL)	-
		JUMLAH	20
PIHAK III/BINATANG	41b	BINATANG (TOKEK ,ULAR) DLL	21
LAYANG-LAYANG	41d	LAYANG-LAYANG (BALIHO DLL)	29

RELE KERJA	KODE
Tidak Termonitor	1
OCR Ø R	3
OCR Ø S	4
GFR	10
OCR GFR	11
OCR GFR Ø S	13
OCR GFR Ø R,T	16
OCR GFR Ø R,S,T	18
OCR Ø R,T >>	24
OCR GFR >>	28
OCR GFR Ø R >>	29
OCR GFR Ø S,T >>	34
OCR GFR Ø R,S,T >>	35